


Index No. J5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 18 Corner common to sections 7, 8, 17, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>BIRCH</u>	<u>BIRCH</u>	<u>POPLAR</u>
<u>5"</u>	<u>8"</u>	<u>9"</u>
<u>N 70 W</u>	<u>N 60 E</u>	<u>S 37 1/2 W</u>
<u>70 LKS</u>	<u>15 LKS</u>	<u>22 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1917 By GLO

Location filed SEC. OF STATE

Monument SET 2X36" I.P. W/BRASS CAP T141N R30W  
57 / 58  
510 / 517  
1917

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker

Found 2" iron monument with brass cap.

Bearing Trees, Reference Objects

Species MORNING GLORY

Diameter 2" BASE

Bearing 1 1/2 HIGH

Distance W. OF COR.

Bearing Trees, Reference Objects

Ash	Red Oak	Red Oak
<u>9"</u>	<u>8"</u>	<u>7"</u>
<u>N 68 W</u>	<u>N 16 E</u>	<u>N 80 E</u>
<u>78.04'</u>	<u>92.60'</u>	<u>68.07'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1989 David Landecker - Certificate  
Doc. # 309833

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_