


Index No. J 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 17 Corner common to sections B, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Poplar</u>	<u>BIRCH</u>	
Diameter <u>10"</u>	<u>8"</u>	
Bearing <u>S 21 E</u>	<u>N 1 E</u>	
Distance <u>53 LKS</u>	<u>72 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By M. A. KEMP
Location filed COUNTY BOOK "C" P 56
Monument FIND 4x4x36" Post - CHECKS WITH ROOTS OF B.T.S

Evidence of Subsequent Corner Restoration

Year of search 1917 By GLO
SET 1x36" 1IP. W/ BRASS CAP 1/4 58
517
1917

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. PINE</u>	<u>6"</u>	<u>S 31 1/2 E</u>	<u>242 LKS</u>
<u>ROAK</u>	<u>10"</u>	<u>N 75 1/2 W</u>	<u>140 LKS</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc # 309834
Set 2"x24" iron monument with brass
cap. TIES: 17" Red Oak N 64 E 90.17'; 8"
Norway Pine S 46 E 96.45'; 22" Norway
Pine S 32 E 159.70' (1917 BT); 9" Norway
Pine S 4 E 64.14'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____