


Index No. L13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1/4 16 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees
Species	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>4"</u>	<u>3"</u>
Bearing	<u>S40E</u>	<u>N30E</u>
Distance	<u>9 LKS</u>	<u>8 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By ELO  
Location filed SEC. OF STATE  
Monument SET 1x36" I.P. W/BRASS CAP PROPORTIONALLY  
14  
516 515  
1917

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker  
Found 1" iron monument with brass cap

Bearing Trees, Reference Objects

	CEDAR	POPULAR
Species	<u>CEDAR</u>	<u>POPULAR</u>
Diameter	<u>5"</u>	<u>5"</u>
Bearing	<u>N15 1/2 E</u>	<u>S57 3/4 W</u>
Distance	<u>88 LKS</u>	<u>23 LKS</u>

Bearing Trees, Reference Objects

	SPRUCE	MAPLE	SPRUCE
Species	<u>SPRUCE</u>	<u>MAPLE</u>	<u>SPRUCE</u>
Diameter	<u>7"</u>	<u>12"</u>	<u>8"</u>
Bearing	<u>N17 W</u>	<u>S66 W</u>	<u>S38 W</u>
Distance	<u>97.77'</u>	<u>85.40'</u>	<u>66.63'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Bill Olerman - 1964  
1989 Certificate - David Landecker  
Doc. # 309839

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_