


Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 24 Corner common to sections 13, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Tree	Distance
<u>TAM.</u>	<u>TAM.</u>		
<u>5"</u>	<u>5"</u>		
<u>S28W</u>	<u>S 1/2 E</u>		
<u>14LKS</u>	<u>11LKS</u>		

Original Bearing Trees Found

Species	Bearing	Tree	Distance
_____	_____		
_____	_____		
_____	_____		
_____	_____		

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set aluminum capped monument on 10' of aluminum rod.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>Burr Oak</u>	<u>Burr Oak</u>	<u>Burr Oak</u>	
<u>15"</u>	<u>7"</u>	<u>8"</u>	
<u>N 8 E</u>	<u>N 54 E</u>	<u>S 76 E</u>	
<u>199.47'</u>	<u>214.24'</u>	<u>328.88'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
_____	_____		
_____	_____		
_____	_____		
_____	_____		

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Certificate - David Landecker
Doc. # 311056

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____