


Index No. P5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 574 Coordinates: X _____ Y _____
E11419 Corner common to sections 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

O = Corner

Species	Bearing	Trees
<u>POPLAR</u>	<u>OAK</u>	
Diameter <u>8"</u>	<u>10"</u>	
Bearing <u>N84E</u>	<u>S32 1/2 W</u>	
Distance <u>24 LKS</u>	<u>19 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 54" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Species	Bearing	Trees, Reference Objects
<u>N. Pine</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
Diameter <u>20"</u>	<u>5"</u>	<u>6"</u>
Bearing <u>N2W</u>	<u>N63E</u>	<u>S14W</u>
Distance <u>68.97'</u>	<u>71.90'</u>	<u>15.36'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Certificate - David Landecker
Doc. # 311058

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____