


Index No. R11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N1/4 28 Corner common to sections 2628



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. PINE</u>	
<u>16"</u>	<u>13"</u>	
<u>N7 1/2 W</u>	<u>S 25 E</u>	
<u>134 LKS</u>	<u>9 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 48" iron monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Red Oak</u>	<u>14"</u>	<u>N 38 W</u>	<u>22.09'</u>
<u>Red Oak</u>	<u>7"</u>	<u>N 86 W</u>	<u>26.11'</u>
<u>Burr Oak</u>	<u>10"</u>	<u>S 10 W</u>	<u>10.07'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc # 311066

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____