


Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 27 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>BIRCH</u>	<u>POPLAR</u>	
Diameter <u>9"</u>	<u>7"</u>	
Bearing <u>S 27 E</u>	<u>N 38 W</u>	
Distance <u>19 LKS</u>	<u>21 LKS</u>	

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1989 By David Landecker  
 Location filed \_\_\_\_\_  
 Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Reference Objects
<u>Birch</u>	<u>Birch</u>	<u>N. Pine</u>
Diameter <u>6"</u>	<u>6"</u>	<u>8"</u>
Bearing <u>N 75 W</u>	<u>N 65 E</u>	<u>S 35 W</u>
Distance <u>30.80'</u>	<u>15.85'</u>	<u>76.84'</u>

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 310864

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_