


Index No. R B-16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5th Coordinates: X _____ Y _____
MC# 13 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Species	Bearing	Trees
<u>BIRCH</u>	<u>BIRCH</u>	
<u>8"</u>	<u>6"</u>	
<u>S70W</u>	<u>N60W</u>	
<u>84 LKS</u>	<u>70 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Red Oak</u>	<u>15"</u>	<u>N 70 W</u>	<u>22.24'</u>
<u>Burr Oak</u>	<u>6"</u>	<u>N 60 E</u>	<u>17.03'</u>
<u>Maple</u>	<u>5"</u>	<u>S 80 E</u>	<u>19.84'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311068

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____