


Index No. T 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 574 Coordinates: X _____ Y _____
E 114 29 Corner common to sections 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>R. OAK</u>	<u>Y. PINE</u>	
<u>10"</u>	<u>12"</u>	
<u>S 4 E</u>	<u>N 68 W</u>	
<u>16 LKS</u>	<u>7 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landscker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. Pine</u>	<u>R. OAK</u>	<u>R. OAK</u>
<u>20"</u>	<u>6"</u>	<u>10"</u>
<u>N 77 W</u>	<u>S 35 W</u>	<u>N 79 E</u>
<u>18.47'</u>	<u>5.57'</u>	<u>39.57'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landscker
Doc. # 310871

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____