


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 114 33 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	<u>BIRCH</u>	<u>Y. PINE</u>	
Diameter	<u>10"</u>	<u>9"</u>	
Bearing	<u>N 27 E</u>	<u>S 41 W</u>	
Distance	<u>26 US</u>	<u>44 US</u>	

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 2" x 54" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>Basswood</u>	<u>R. Oak</u>
Diameter	<u>17"</u>	<u>10"</u>	<u>14"</u>
Bearing	<u>N 68 W</u>	<u>N 22 E</u>	<u>S 23 E</u>
Distance	<u>67.23'</u>	<u>105.72'</u>	<u>43.91'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 310875

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_