


Index No. V 15-16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
MC # 7 Corner common to sections 27, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>W. PINE</u>	<u>oak</u>
Diameter	<u>24"</u>	<u>8"</u>
Bearing	<u>N 70 E</u>	<u>S 10 E</u>
Distance	<u>103 lks</u>	<u>97 lks</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set a "x 48" iron pipe with brass cap, plastic base and magnet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

	Bearing Trees	Reference Objects
Species	<u>Birch</u>	<u>Burr Oak</u> <u>Birch</u>
Diameter	<u>10"</u>	<u>16"</u> <u>7"</u>
Bearing	<u>N 72 E</u>	<u>S 75 E</u> <u>S 5 E</u>
Distance	<u>29.76'</u>	<u>16.11'</u> <u>31.52'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 310879

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____