


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM.</u>	<u>TAM.</u>	_____	_____
Diameter	<u>5"</u>	<u>18"</u>	_____	_____
Bearing	<u>N 5 1/2 W</u>	<u>S 3 W</u>	_____	_____
Distance	<u>15 LKS</u>	<u>35 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By E. B. HORST
Location filed COUNTY RESURVEY "E-30"
Monument IRON MONUMENT - 6x4x4 B.T.S.
1920, E. B. HORST, BOOK "C" P. 466 FND CORNER

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker
Set 10' aluminum rod with aluminum cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>Birch</u>	<u>Burr Oak</u>
<u>19"</u>	<u>7"</u>	<u>11"</u>
<u>S 58 E</u>	<u>S 45 E</u>	<u>S 3 W</u>
<u>127.64'</u>	<u>93.16'</u>	<u>117.77'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 310882

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____