


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>YILNE</u>	<u>YILNE</u>	<u>OAK</u>	<u>POPLAR</u>
Diameter <u>13"</u>	<u>16"</u>	<u>10"</u>	<u>14"</u>
Bearing <u>S33W</u>	<u>N51 1/2 W</u>	<u>S30E</u>	<u>N31E</u>
Distance <u>29 LKS</u>	<u>32 LKS</u>	<u>54 LKS</u>	<u>99 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Found 2" iron monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Species	Bearing	Trees	Reference Objects
<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>7"</u>	<u>23"</u>	<u>6"</u>	<u>6"</u>
Bearing <u>S58W</u>	<u>N42W</u>	<u>N88E</u>	<u>S25E</u>
Distance <u>31.25'</u>	<u>145.95'</u>	<u>92.63'</u>	<u>20.53'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OCKERMAN - 1964
1989 Certificate - David Landecker
Doc. # 310874

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____