


Index No. 221

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
SE 35 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. PINE</u>	<u>N54</u>	
Diameter <u>8"</u>	<u>9"</u>	
Bearing <u>N81W</u>	<u>N57E</u>	
Distance <u>7743</u>	<u>15435</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landscker
Location filed _____
Monument found 2" iron monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Ash</u>	<u>Ash</u>	<u>Ash</u>
Diameter <u>8"</u>	<u>11"</u>	<u>5"</u>
Bearing <u>N64W</u>	<u>N1E</u>	<u>N56E</u>
Distance <u>27.93'</u>	<u>54.01'</u>	<u>39.94'</u>

(1965 BT)

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - DITZLER'S RAINFOREST
WALTER E. CURD. 1976

CERTIFICATE - BILL OKERMAN - 1965

1989 Certificate - David Landscker
Doc. #311189

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____