


Index No. B 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
C.A. 116 Corner common to sections 1



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1 X 36" I.P. w/ Brass N 116 1 51
CAD 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. PINE BROOK _____
Diameter 5" 12" _____
Bearing N 57 E S 61 W _____
Distance 250 LKS 313 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By Rit. Schneider - 1977
Plat - Baywood -

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____