Index No. D21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

5/16 Corner common to sections 1, 2



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1x36" Tip. w/ Brass Cap

5/16
52/51
1917

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species Mound of Stone

Diameter 2' BASE

Bearing 1½' HIGH

Distance W. OF COR.

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1914 By CURO

Location filed microfilm - roll 115 BK92 P. 88-89

Monument Set 2X48" galv. tip. w/ Cap in mound

Corner sets in a revene

Evidence of Subsequent Corner Restoration

Year of search 1987 By Walter Curo

Found 2" capped galvanized iron pipe up 20" and 1" GLO brass cap monument alongside North up 10".

Bearing Trees, Reference Objects

Species	Burr Oak	Red Oak	Red Oak
Diameter	9"	13"	8"
Bearing	N 16 E	S 60 E	S 3 E
Distance	14.80'	53.80'	58.92'

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Certificate - Walter Curo
Doc. #309688

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____