


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 7 Corner common to sections 6, 7



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

	Bearing	Trees	
Species	<u>Y. PINE</u>	<u>Y. PINE</u>	<u>W. PINE</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>16"</u>
Bearing	<u>S16E</u>	<u>N32E</u>	<u>N25W</u>
Distance	<u>151 LKS</u>	<u>189 LKS</u>	<u>35 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD
 Location filed COUNTY RESURVEY PLAT "E-51"
 Monument 2 1/4 X 4 1/8" IRON MONUMENT
1915, MILLER, BOOK "C" P. 574 FND STUMPS OF SE, NW,
NE, B. T. SET STAKE
also on microfilm - roll 105 BK 58 P. 30, 35 (50)

Bearing Trees, Reference Objects 72 (87)

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1916 By H. E. Baldwin
microfilm - roll 115 BK 86 P. 26
Fnd F.M. set by County Surveyor John Curd

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

(E-1)

Subsequent Corner Restoration

Year surveyed 1978 By USFS
 Location filed Cass Lake
 Monument Witnessed corner as follows:
6" W. Pine N26°W 97.60'
18" N. Pine S68°E 92.56'
8" J. Pine S47°W 52.73'

1978 Cass Co. Hwy. Dept. found brass
cap RLS 12261 and witnessed:
8" W. Pine N14 81.8'
8" Oak SE 1/4 54.7'
6" J. Pine SW 1/4 64.5'

8/92 CCHD Alignment book set
County Aluminum cor flush with
Bit surface.

1994 USFS added the following
14" W. Pine N18°W 91.73'
16" N. Pine N46°E 171.60'

7/05 CCSO found Alum cap and
USFS witnesses, GPS monument,
#2005.031.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____