


Index No. ER3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 574 Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 1112



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>JULINE</u>	<u>POPULAR</u>	_____
Diameter	<u>6"</u>	<u>7"</u>	_____
Bearing	<u>S 31 W</u>	<u>S 67 E</u>	_____
Distance	<u>17 LKS</u>	<u>19 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed SEC. OF STATE
Monument SET 1 X 3/8" I.P. W/BRASS CAP.
1/4 51
512
1917

Evidence of Subsequent Corner Restoration

Year of search 1962 By Pete Meyer
Found GLO monument in good condition;
8" W. OAK S 72 1/2 W 49.50' now 17".

Bearing Trees, Reference Objects

Species	<u>W. OAK</u>	<u>W. OAK</u>	_____
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>N 61 1/2 W</u>	<u>S 72 1/2 W</u>	_____
Distance	<u>55 LKS</u>	<u>75 LKS</u>	_____

Bearing Trees, Reference Objects

Species	<u>OAK</u>	<u>OAK</u>	_____
Diameter	<u>12"</u>	<u>6"</u>	_____
Bearing	<u>N 12 E</u>	<u>S 46 E</u>	_____
Distance	<u>21.0'</u>	<u>43.5'</u>	_____

Subsequent Corner Restoration

Year surveyed Apr 2002 By J. Freeman #21367
Location filed CCSO
Monument Cert. of Surv. shows Mon. Found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____