


Index No. E3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
N 74 7 Corner common to sections 6, 7



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees	
Species <u>J. PINE</u>	<u>W. PINE</u>
Diameter <u>8"</u>	<u>18"</u>
Bearing <u>S 16 W</u>	<u>N 32 W</u>
Distance <u>22 US</u>	<u>19 US</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO

Location filed COUNTY RESURVEY PLAT "E-51"

Monument 2 1/4 x 4 1/2" IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1959 By Harold Curo

Found 2 1/2 x 4 1/2" capped iron monument

also on microfilm - 1915 Scott set J.M.
Roll 105 BK 58 P 71(86)

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

<u>J. PINE</u>	<u>W. OAK</u>	<u>Red OAK</u>
<u>20"</u>	<u>6"</u>	<u>7"</u>
<u>N 50° 19' E</u>	<u>N 68° 56' E</u>	<u>S 4° 51' W</u>
<u>44.65'</u>	<u>65.60'</u>	<u>48.40'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - HAROLD CURO - 1959

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____