


Index No. F 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 57H Coordinates: X _____ Y _____
N¹¹⁶ Corner common to sections 2 and 7-141-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 N¹¹⁶
Original monument 1x36" IR. W/BRASS 512/57
CAP 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species N. PINE W. OAK _____
Diameter 8" 3" _____
Bearing S10 1/2 E S77 1/2 W _____
Distance 192 LKS 75 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER
Location filed _____
Monument Found GLO monument in good
condition; 6" J. Pine N43 1/2 E 69.98' now
stump hole; 6" J. Pine S70 3/4 W 12.54' now
stump.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Cedar Post _____
Diameter 4x4x72" _____
Bearing North _____
Distance 2.9' _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1963 Certificate - Pete Meyer
Mar 1998 T. Freeman #21367
Cert of Surv. shows Mon. Found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____