Index No. F5

CASS COUNTY LAND CORNER RECORD

T. 141 N/16 R. 31 M. 5TH Coordinates: X _____ Y _____

Corner common to sections 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species			
Diameter			
Bearing			
Distance			

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Monument Found 2" iron pipe. Set 2"x5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	J. Pine	J. Pine	
Diameter	13"	16"	
Bearing	S 88½ W	S 56 E	
Distance	26.3'	6.15'	

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____