


Index No. 65

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
E/47 Corner common to sections 7, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By SCOTT
Location filed COUNTY BOOK "C" P. 579
Monument SET T.M.

Evidence of Subsequent Corner Restoration

Year of search 1959 By Harold Curn
Found 2 1/2 x 4 1/8" capped galvanized iron monument.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>W. PINE</u>	<u>N. PINE</u>	<u>Cedar Post</u>
<u>6"</u>	<u>14"</u>	<u>4x4x100"</u>
<u>N. 59° 32' W</u>	<u>N. 24° 15' W</u>	<u>S. 9° 50' W</u>
<u>45.80'</u>	<u>60.35'</u>	<u>22.25'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURN - 1959 WITNESS 815' W.
" 176' S.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____