


Index No. H 22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S.W. 1/16 Corner common to sections 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument N 36° 11' W / BRASS SW 1/16 S12  
cap 1917

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing Trees	
Species	<u>W. Pine</u>	<u>Poplar</u>	_____
Diameter	<u>18"</u>	<u>12"</u>	_____
Bearing	<u>S 56 1/4 E</u>	<u>S 71 3/4 W</u>	_____
Distance	<u>152 LKS</u>	<u>138 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition; 18" W. Pine S 56 1/2 E 100.32' now 25"

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>B. Pine</u>	<u>Oak</u>	_____
Diameter	<u>25"</u>	<u>4"</u>	_____
Bearing	<u>S 54 E</u>	<u>S 49 1/2 W</u>	_____
Distance	<u>100.4'</u>	<u>27.6'</u>	_____

(1917 BT)

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962