


Index No. J 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 13 Corner common to sections 1213



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Bearing Trees

Species	<u>POPULAR</u>	<u>POPULAR</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>S 16W</u>	<u>N 20E</u>	_____
Distance	<u>21 LKS</u>	<u>15 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed SEC. OF STATE
Monument SET 1x36" I.P. W/BRASS CAP PROPORTIONALLY

1/4 512
513
1917

Evidence of Subsequent Corner Restoration

Year of search 1977 By Milo Stefan
Set 6x6x24" concrete post with brass cap.

Bearing Trees, Reference Objects

Species	<u>PINE</u>	<u>ASPEN</u>	_____
Diameter	<u>12"</u>	<u>3"</u>	_____
Bearing	<u>N 8 3/4 E</u>	<u>S 61 1/2 W</u>	_____
Distance	<u>195 LKS</u>	<u>13 LKS</u>	_____

Bearing Trees, Reference Objects

<u>B. OAK</u>	<u>W. OAK</u>	<u>ASH</u>	_____
<u>6"</u>	<u>6"</u>	<u>4"</u>	_____
<u>S 52 E</u>	<u>S 60 E</u>	<u>S 25 W</u>	_____
<u>45.88'</u>	<u>45.82'</u>	<u>26.12'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1977 FILED IN 1980
Doc. # 258608

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____