


Index No. 524

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
E¹¹⁶ Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 E¹¹⁶ 512
Original monument 1x36" l.p. w/ BRASS CAP 513
1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species R.OAK W.OAK _____
Diameter 12" 10" _____
Bearing N9W S17 1/2 E _____
Distance 250LKS 240LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 4/19/85 By Cass Co. & USFS
Found stub of 1918 B.T. w. oak SE l.p. gone

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

6/26/85 - set 2" x 2" l.p. w/ marked brass cap,
mid way between 14 and section corner, but 2
S. of line - holding distance from 620 oak
Red oak - Triple 11" - (S. tree) 6" 5" 20" oak stub
N6°W S42°W S 3°E 516E
140.10 55.77' 70.66' 158.40'
scribed B.T. scribed E¹¹⁶ S.13 B.T.

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1985 Doc# 292692

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____