


Index No. N 4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 574 Coordinates: X _____ Y _____
EAST 116 Corner common to sections 18, 19



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer
Location filed _____
Monument Found 1 3/4" x 48" iron pipe. Set
2" x 5' galvanized wrought iron pipe filled
with concrete and capped with 3" stamped
bronze tablet.

Bearing Trees, Reference Objects

Species Oak
Diameter 8"
Bearing S 44 W
Distance 37.9'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____