


Index No. P 1

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
W 14 19 Corner common to sections 19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Bearing Trees	
Species <u>ASPEN</u>	<u>Y. PINE</u>
Diameter <u>8"</u>	<u>10"</u>
Bearing <u>N65E</u>	<u>S40W</u>
Distance <u>5 LKS</u>	<u>19 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1967 By DNR-Engineering

Location filed Map's notes in file

Monument found corner

Evidence of Subsequent Corner Restoration

Year of search 1962 By PETE MEYER

Found 2" capped iron pipe; 10" Y. Pine
S40W 12.54' now stump.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>Steel post</u>	<u>Steel post</u>
<u>72"</u>	<u>72"</u>
<u>East</u>	<u>North</u>
<u>3.4'</u>	<u>2.5'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Aug. 1919, Twp ord shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____