


Index No. R 19

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X ^{Long} 94°33'59.0830" Y ^{Lat} 47°00'36.6183"
N1426 Corner common to sections 23, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species POPLAR POPLAR _____
Diameter 3" 3" _____
Bearing N9E S43E _____
Distance 17KS 3KS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By E. B. HORST
Location filed COUNTY RESURVEY PLAT "E-53"
Monument 2x48" IRON MONUMENT BASED ON JUNE 1920 SURVEY RECORD NO. 467, BOOK C, PG 460, ESTABLISHED AS LOST - NO TRACE OF OLD

Evidence of Subsequent Corner Restoration

Year of search 1958 By Harold Curo
Set 2 3/4 x 60" capped monument filled with concrete.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

N. Pine R. Oak R. Oak
22" 4" 7"
N34° 56' W N39° 29' E S31° 46' W
29.80' 28.60' 24.80'

R-19

Subsequent Corner Restoration

Year surveyed 1980 By USFS
Location filed Cass Lake Office
Monument Found IP in road, cap sheared off, Set USFS brass cap monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1958

7/2001 LEA; Freeman found 1980 monument, on S, down 0.5', the 1958 witness are as follows:

24" N. Pine N35°W, 30.05' (1958)
10" R. Oak N39°E, 28.40' (1958)
15" R. Oak S32°W, 24.65' (1958)
Sign Post South 23.6'

Remonumentation certificate prepared 11/1/01
Filed at Cass Co. Recorder #442510

By Freeman
Date _____