Index No. S-T 3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections _____

N. OF C 1/4



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1959 By Harold Curo

Location filed _____

Monument Set 2 3/4 x 60" capped monument Filled with concrete.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Cedar Post	Cedar Post		
Diameter	4x4x100"	4x4x100"		
Bearing	N45° 13'E	N14° 23'W		
Distance	19.30'	20.20'		

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - HAROLD CURO - 1959

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____