


Index No. T1

CASS COUNTY LAND CORNER RECORD

T. 14 R. 31 M. 5TH Coordinates: X _____ Y _____
W 1/4 30 Corner common to sections 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Y. PINE</u>	<u>W. PINE</u>	
<u>8"</u>	<u>9"</u>	
<u>N 85 E</u>	<u>S 55 W</u>	
<u>14 LKS</u>	<u>35 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HORST
Location filed COUNTY RESURVEY PLAT E-54
Monument IRON MONUMENT
1921, E. B. HORST, BOOK "C" P. 453 SET WOOD STAKE, P. 456
SET 2x40" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1984 By Tony Kerrick
Corner Certificate
Find 3" brass cap set. n 1958 by Harold Curo

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Cedar post</u>	<u>w. oak</u>	<u>w. oak</u>	<u>w. oak</u>
<u>4x4</u>	<u>14"</u>	<u>TWIN 12"</u>	<u>8"</u>
<u>N 83 E</u>	<u>S 27 E</u>	<u>S 6 E</u>	<u>S 39 W</u>
<u>14.65'</u>	<u>38.29'</u>	<u>34.66'</u>	<u>17.93'</u>
			<u>8.40'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1958
Certificate - Tony Kerrick - 1984
Doc # 280486

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____