


Index No. T 4-5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections _____
ON E-W 1/4 LINE ON E. SIDE HOWARD LAKE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1959 By Harold Curo
Location filed _____
Monument Set 2³/₄ x 60" capped monument
filled with concrete.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Elm</u>	<u>W. Pine</u>
Diameter	<u>16"</u>	<u>12"</u>	<u>20"</u>
Bearing	<u>N1°48'E</u>	<u>N49°53'E</u>	<u>S50°57'E</u>
Distance	<u>54.30'</u>	<u>46.00'</u>	<u>42.50'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD Curo - 1958

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____