


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
MC# 15 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>J. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>S 42° W</u>	<u>S 20° E</u>	_____
Distance	<u>15 LKS</u>	<u>12 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK "A" P 386-387
Monument SET 2x48" CAPED GALV. I.P. FROM OLD GOVT BITS
1912, JOHN CURD, BOOK "B" P 418-420 FND OLD GOVT BITS AND 2x48" GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1921, 1922 By E. B. HORST
COUNTY RESURVEY PLAT "E-53" I.M.
1920, E. B. HORST, BOOK "C" P 463 FND I.M.
1916 - Horst - microf. I.M. - roll 115 BK 80 P. 33 Fnd I.M.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

T, U - 21

Subsequent Corner Restoration

Year surveyed 1976 By CO HWY DEPT
Location filed CO RD # 50
Monument 2 1/2 x 48" I.M.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - CRESCENT BEACH
JOHN M. GREENE 1920?

1/03 CCSO found 2" ODIP w/plumber cap, up 0.5', on back side of ice ridge, 15' E S. of Lake. Witness as follows.

PLAT - CRESCENT BEACH FIRST ADDITION
JOHN W. CURD 1936

16" N. Pine S 85° W 14.38' to dbl hd nail
10" W. Pine S 22° W 19.77' to dbl hd nail
8" W. Pine S 88° E 4.70' to dbl hd nail

Jan. 8, 2003 B. Kovanen # 16459 CCSO
CCRO # A000482297

2" ODIP with plumbers cap, up 0.5', 15', more or less, south of the shore of Portage Lake.

Bearing Trees

RED PINE	W. PINE	W. PINE
<u>16"</u>	<u>10"</u>	<u>8"</u>
<u>S 85° W</u>	<u>S 22° W</u>	<u>S 88° E</u>
<u>14.38'</u>	<u>19.77'</u>	<u>4.70'</u>

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____