


Index No. V 4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/16 Corner common to sections 30, 31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer
Location filed _____
Monument Found 1 3/4" iron pipe. Set 6" x 5' cylindrical concrete monument with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Cedar Post</u>
Diameter	<u>6"</u>	<u>4x4x72"</u>
Bearing	<u>S 4 1/2 E</u>	<u>N 79° 30' E</u>
Distance	<u>93.3'</u>	<u>2.35'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - PETE MEYER - 1962

Plat - Howard Lake Shores - G.H. Stevenson 1961

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____