


Index No. X 3-4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 57A Coordinates: X _____ Y _____

5m Corner common to sections 31
ONE-W¹/₄ LINE - E. SIDE HOWARD LAKE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1959 By Harold Curo
Location filed _____
Monument Set 2³/₄ x 60" capped monument filled with concrete.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Elm Elm W. Pine
Diameter 6" 12" 9"
Bearing N29°45'E N74°23'E S24°08'W
Distance 10.80' 41.00' 9.00'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1959
Plat - Howard Lake Shores - G.H. Stevenson - 1961

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____