


Index No. X4

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 57A Coordinates: X _____ Y _____
C.E. 116 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER
Location filed _____
Monument Found 1 3/4" iron pipe Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species J. Pine
Diameter 12"
Bearing N10 1/2 E
Distance 19.3'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____