


Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 31 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>SOFT PINE</u>	<u>LYNN</u>
Diameter	<u>5"</u>	<u>6"</u>
Bearing	<u>N 70 E</u>	<u>S 6 W</u>
Distance	<u>15 KS</u>	<u>19 KS</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HORST  
Location filed COUNTY RESURVEY PLAT "E-55"  
Monument IRON MONUMENT  
1921, E. B. HORST, BOOK "C" P. 453 TWO BIRCH STUMP FOR BIT.  
AND TWO CORNER. P. 456 SET 2x4 1/2" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1984 By Tony Kerick  
Corner Certificate  
Find 3" brass cap set by Pete Meyer in 1962  
and his accessories

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>oak</u>	<u>steel sign post</u>	<u>Maple</u>	<u>steel sign post</u>
<u>19"</u>	<u>9"</u>	<u>6"</u>	<u>8"</u>	<u>8"</u>
<u>S 73 E</u>	<u>S 74 W</u>	<u>North</u>	<u>S 14 W</u>	<u>East</u>
<u>32.50'</u>	<u>21.20'</u>	<u>1.75'</u>	<u>36.04'</u>	<u>3.79'</u>
<u>R 1962 trees 1</u>				

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962  
Certificate - Tony Kerick - 1962  
Doc. # 280494

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_