


Index No. Y 1-2

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 57H Coordinates: X _____ Y _____

SMC Corner common to sections _____
ON S¹¹⁶ LINE - W. BANK HOWARD LAKE



EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Monument Found 1 1/2" iron pipe. Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet 5.7' west of found SMC.

Bearing Trees, Reference Objects

Species Ash Elm

Diameter 5" 10"

Bearing N60W S42W

Distance 34.4' 37.0'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETER METER - 1962

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____