


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X Y
N 1/4 4 Corner common to sections 4 AND 33-143-25



EXISTING SURVEYS

Original Government Survey
Year surveyed 1871
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species MAPLE FIR
Diameter 6" 4"
Bearing N89W S80E
Distance 8CKS 12WS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument Found Swamp Hole of Butabits Set 2 1/2 x 28" Alum Post w/ Alum cap
T143N R25W
14 533
54

Evidence of Subsequent Corner Restoration
Year of search 1985 By J. Klenot, et al
Certificate of survey indicates BLM monument.

Bearing Trees, Reference Objects T142N 1976
Species BASWOOD MAPLE
Diameter 15" 12"
Bearing N86E S20W
Distance 19CKS 33CKS

Bearing Trees, Reference Objects

A-11

Subsequent Corner Restoration
Year surveyed 1979 By G. Stevenson
Location filed Landecker & Assoc. Walker Office
Monument Found Alum. cap, Alum. pipe.

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

1999 Landecker & Assoc. plat Peterson Sugar Lake Add. shows iron in place.

1/2002 Landecker & Assoc. found 2 1/2" Alum. post with Alum. cap, 84' ± SW of 2, and BLM 1976 witnesses, add the following:

Sign Post East 2.4'
Certificate filed

Remonumentation certificate prepared ✓
Filed at ECRO document # 461717

By RLS 17008
Date 1/29/03