Index No. A 13-14

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____

MC# 4 Corner common to sections 3 AND 34-143-25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	CEDAR	SPRUCE		
Diameter	6"	10"		
Bearing	S3E	NORTH		
Distance	9LKS	3LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed May 2003 By T. Freeman #21367

Location filed

Monument Cert. of Svy. shows Mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____