


T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____
N14 3 Corner common to sections 3 AND 34-143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species MAPLE FIR _____
Diameter 6" 8" _____
Bearing N62E S34W _____
Distance 1145 1645 _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument SET 2 1/2 X 28" ALUM POST W/ALUM CAP T143 NR 2500
1/4 534
53
T142N
1976

Evidence of Subsequent Corner Restoration

Year of search 1990 By LANDECKER INC.
FOUND 2 1/2" ALUM MON BY BLM +
BOTH BLM BT'S
SET 8' STEEL SIGN POST 3.0 EAST

Bearing Trees, Reference Objects
Species ASPEN ASPEN _____
Diameter 12" 12" _____
Bearing N42E S45W _____
Distance 1545 2745 _____

Bearing Trees, Reference Objects
MAPLE ASPEN MAPLE ASPEN
7 12 7 13
N51W N47E S55E S42W
47.34 10.06 24.15 18.00
(1976) (1976)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Aug 2002 L. Leulling 16089
Cert. of Svy. shows mon. Found.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CHRT. BY LANDECKER 1990
DOC. # 325280