


Index No. A3

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____
N114 6 Corner common to sections 6 AND 31-143-25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species CEDAR SPRUCE
Diameter 6" 9"
Bearing N10E S27W
Distance 8 LKS 23 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1976 By ALM
Location filed SEC. OF STATE
Monument FNO 2 1/2" I.P. W/ BRASS CAP SET BY U.S.F.S. T143NR256

Evidence of Subsequent Corner Restoration

Year of search 1966 By Milo Stefan
Set 2" x 60" galvanized steel pipe with bronze cap.

14 531
56

T142N
1966

Bearing Trees, Reference Objects

Species CEDAR CEDAR CEDAR STEEL SIGNPOST
Diameter 10" 8" 8" 54-2 x 54-4'
Bearing N31E S48W N77W EAST
Distance 11 LKS 20 1/2 LKS 13 LKS 8 1/2 LKS

Bearing Trees, Reference Objects

Cedar Cedar Cedar
8" 8" 10"
S48W N77W N31E
13.50' 8.50' 7.40'

U.S.F.S. TIES

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1966 FILED IN 1979
Doc. # 246233

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____