


Index No. R7

CASS COUNTY LAND CORNER RECORD

142 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 29 Corner common to sections 20, 29



○ = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1871  
 Original monument Post

Species	Bearing	Trees
<u>BIRCH</u>	<u>BIRCH</u>	
Diameter <u>8"</u>	<u>9"</u>	
Bearing <u>N18W</u>	<u>S81W</u>	
Distance <u>108LKS</u>	<u>123LKS</u>	

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**  
 Year surveyed 1985 By Roger Mustonen  
 Location filed Corner Certificate - Doc # 286239  
 Monument Set 2" Sq. Steel monument w/ stamped aluminum cap proportionally between NE & NW Sec. corners

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Trees, Reference Objects
<u>Poplar</u>	<u>5"</u>	<u>Cedar</u>
Diameter <u>5"</u>	<u>7"</u>	<u>sign post</u>
Bearing <u>N14E</u>	<u>S17E</u>	<u>East</u>
Distance <u>11.89'</u>	<u>64.82'</u>	<u>1'</u>

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Roger Mustonen - 1985

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_