


Index No. K 5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____
E114 31 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>MAPLE</u>	<u>MAPLE</u>	
<u>6"</u>	<u>0"</u>	
<u>S56W</u>	<u>N86E</u>	
<u>18'KS</u>	<u>33'KS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By J.H. FLOW
Location filed COUNTY BOOK "D" P. 71
Monument SET 1 1/2 X 4 1/4" FLUE PIPE

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>ASPEN</u>	<u>ASPEN</u>	
<u>6"</u>	<u>6"</u>	
<u>S7W</u>	<u>N70E</u>	
<u>48'</u>	<u>50.5'</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____