


Index No. A 73

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 Corner common to sections LAND 36-143-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>BIRCH</u>	<u>W. PINE</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>S 68 E</u>	<u>N 25 W</u>	_____
Distance	<u>20 LKS</u>	<u>17 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By Wm. OSUPSEN  
Location filed \_\_\_\_\_  
Monument 2" x 6" BR/CMP

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

STEEL SIGN POST'S 4.0 NORTH AND 3.9 EAST

Bearing Trees, Reference Objects

Species	<u>RED OAK</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N 59 E</u>	<u>S 15 E</u>	<u>S 71 W</u>
Distance	<u>57.48</u>	<u>22.18</u>	<u>26.60</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1963  
Doc. # 319603

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_