

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 14R R. 26 M. 5TH Coordinates: X _____ Y _____
NE 6 Corner common to sections 5, 6 AND 31, 32-143-26



O = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1872
Original monument Post

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	<u>IRONWOOD</u>
Diameter <u>12"</u>	<u>10"</u>	<u>12"</u>	<u>6"</u>
Bearing <u>S14W</u>	<u>N21W</u>	<u>N33E</u>	<u>S74E</u>
Distance <u>23 LKS</u>	<u>25 LKS</u>	<u>30 LKS</u>	<u>13 LKS</u>

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURA, HARRY TODD
Location filed COUNTY SURVEY RECORD BOOK "A" P. 581-583
Monument FND OLD GOVT BITS: 10" W. PINE N31W 25LKS, 12" W. PINE N33E 30LKS, STUMP 12" W. PINE S14W 23LKS
SET 1 X 24" DRIFF BELT.
1915 JOHN CURA BOOK "B" P. 81-85 FND CORNER SET ABOVE

Year of search 1982 By CA HWY & SURVEYOR
FND NOTHING.
1915 - P.M. SCOTT - microfilm - roll 115 BK 71 P. 94
Fnd corner set by Cura in 1911
same as Book "B" P. 81-85

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>IRONWOOD</u>	<u>MAPLE</u>	_____
Diameter <u>4"</u>	<u>10"</u>	_____
Bearing <u>S38-26W</u>	<u>S37-28E</u>	_____
Distance <u>75.20'</u>	<u>78'</u>	_____

* 1915 BITS: A

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

A-5

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 5/04 By CCSO
Location filed # 2004.001
Monument Found USFS Brass cap, flush, on E of Co. Rd. #4. USFS
trees good, except SE, add:
10" R. OAK S55°E 95.01 to dhn

Year of search _____ By _____
Certificate - Ken Whitehorn - USFS - 1986
Doc. # 289607
Set corner in E of Rd i fence W.
8' Steel post N61°W 72.05'
8' Steel post N57°E 69.82'
14.8" R. oak S47°E 88.04'
15.2" R. oak S42°W 99.95'