


Index No. A 6-7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
MC # 44 Corner common to sections 5 AND 32-143-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BIRCH</u>	_____	_____
Diameter	<u>10"</u>	_____	_____
Bearing	<u>N 80 W</u>	_____	_____
Distance	<u>50 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By WM. OSVENSEN
 Location filed _____
 Monument WC MC SET A 2" x 48" BR/CR
ON TOP OF 8' STEEL SIGN POST RELOC
SET 8' STEEL SIGN POSTS 2' WEST, 4' EAST

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>RED OAK</u>	<u>MAPLE</u>	<u>MAPLE</u>
Diameter	<u>8</u>	<u>7</u>	<u>5" TWIN</u>
Bearing	<u>N 74 W</u>	<u>S 4 E</u>	<u>S 75 W</u>
Distance	<u>66.68</u>	<u>32.12</u>	<u>26.50</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT BY WM OSVENSEN 1990
Doc. # 325469

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____