


Index No. A7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 37A Coordinates: X _____ Y _____

N 14 5 E Corner common to sections 5 AND 32-143-26

M.C. 45



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>ASPEN</u>	<u>BIRCH</u>	_____
Diameter	<u>12"</u>	<u>8"</u>	_____
Bearing	<u>N67E</u>	<u>S33E</u>	_____
Distance	<u>13 LKS</u>	<u>17 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By _____
Location filed _____
Monument CO SURVEY BK 7 BOX 2 OF CO
DITCH SURVEY BOOKS, PG 55

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSVESEN
END 1 1/2" IRON PIPE ADD ALUM CAP TO
EXISTING PIPE
SET 8' STEEL SIGN POSTS 7.8 WEST, 4.3 EAST

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>BASSWOOD</u>	<u>PINE STUMP</u>	<u>OAK</u>	<u>OAK</u>
<u>8</u>	<u>12</u>	<u>7"</u>	<u>7"</u>
<u>N56E</u>	<u>S71E</u>	<u>S20W</u>	<u>S74W</u>
<u>10.46</u>	<u>81.6</u>	<u>29.52</u>	<u>16.79</u>

(1916)

Subsequent Corner Restoration A-7

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. BY WM. OSVESEN
Doc # 325/59

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____