


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X NE 5 Y 4, 5 AND 37, 33 - 143-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trunks	
<u>BIRCH</u>	<u>R. OAK</u>	<u>BIRCH</u>	<u>ELM</u>
<u>6"</u>	<u>14"</u>	<u>8"</u>	<u>6"</u>
<u>N47E</u>	<u>N21W</u>	<u>S54E</u>	<u>S68W</u>
<u>3 LKS</u>	<u>22 LKS</u>	<u>17 LKS</u>	<u>18 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Co DITCH SURVEY BK 7 BOX 2 OF  
Co DITCH SURVEY BOOKS, PG 55

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM OSURSEN  
FIND 1/2" PIPE LYING ON GROUND  
SET 2" X 48" BR/CP MON  
SET 8' STEEL SIGN POSTS WEST 4.6, EAST 3.7

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

W. OAK	W. OAK	W. OAK	W. OAK
<u>6"</u>	<u>4"</u>	<u>8"</u>	<u>12"</u>
<u>N14W</u>	<u>N14E</u>	<u>S54E</u>	<u>S43W</u>
<u>15.66</u>	<u>31.93</u>	<u>12.03</u>	<u>12.58</u>

Subsequent Corner Restoration A 9

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERT BY WM OSURSEN 1990  
Doc. # 325160

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_