


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
E/4 2 Corner common to sections 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Species	Bearing	Trees
<u>IRONWOOD</u>	<u>S9E</u>	<u>SPRUCE</u>
<u>4"</u>	<u>542W</u>	<u>7LKS</u>
<u>5"</u>		
<u>8LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997, 7-22 By Laverne Leuelling
Set brass capped galvanized steel pipe at
single proportioned position between NE & SE
corners of Section 2.

Cert. Filed 12-8-97, Doc. #395044

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Basswood</u>	<u>0.203m</u>	<u>N20W</u>	<u>13.754m</u>
<u>Triple Basswood</u>	<u>0.279m</u>	<u>S61W</u>	<u>7.578m</u>
<u>Maple</u>	<u>0.254m</u>	<u>S04E</u>	<u>14.458m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____