

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. C5

CASS COUNTY LAND CORNER RECORD

T. 147 R. 26 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E114 6 Corner common to sections 5, 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees			
Species	<u>W. PINE</u>	<u>W. PINE</u>	
Diameter	<u>6"</u>	<u>8"</u>	
Bearing	<u>S75E</u>	<u>S15W</u>	
Distance	<u>7 LKS</u>	<u>6 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Co DITCH SURVEY BK 7 BOX 2  
OF Co DITCH SURVEY BOOKS, PG 25

Evidence of Subsequent Corner Restoration

Year of search 1/05 By CCSO  
Set Alum. County monument,  
up 0.5', at East edge of small  
hog.

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>	<u>R. Oak</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N88°E</u>	<u>S5°W</u>	<u>S45°W</u>
Distance	<u>28.97'</u>	<u>28.34'</u>	<u>60.16'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

\* distance to double head nail

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_